ers (1.3) is suffer inglands absended	JLASSIFIE	o message — T	Care service in a	PF2 752 (17 ) Sec. (Securioris)	venebook (
DATE 2147Z 23 DEC 64	S E (	. i-	2	9 10	e en santante
25 <del>X1A</del>	phy commenced by the second of the commenced of the second			12	
TO : DIRECTOR	ROUTIN		5	13 14 15	**************************************
ACTION:	3 - 4 - 5 - 16 - 16 - 1		PRIORITY	October 1975 Control	
TOR 2215Z 23 DEC 64	7			IN 64351	
25X1A	OP 710.	1-1/13			de constant
TO PRIORITY 25X1A OXCART FLIEST OPS	INFO		CITE	003,87	<u>ات</u> 25X1A
25X1A 1. ARTICLE 128	•				\$- .5 .0v. 5
	TAKEOFF AT Ø915 H	OURS, LANDING	AT 1010 H	URS FOR	# 1

- 55 MIBUTES. MISSION UNSUCCESSFUL. GROSS WEIGHT 90,000 LBS, C.G. 21.4 PERCENT, TAKEOFF DISTANCE 7500 FT, TAKEOFF SPEED 210 KNOTS, PRESSURE ALT 4375 FT, TEMP 41 DEGREES, WIND CALM, MAX SPEED 2.80 MACH, MAX ALT74,800 FT, TIME OVER 2.0 MACH:30, TIME OVER 2.6 MACH:20, TOTAL AIRCRAFT TIME 112:53. PURPOSE: FUNCTION CHECK FLIGHT. CONFIGURATION: 2.9 MACH. Q BAY AND SPECIAL EQUIPMENT: NOME.
- 2. HORMAL TAKEOFF AND CLIMB. INS AUTOMAV- AUTO DESTINATION USED AND APPEARED GOOD. 3 AD°S WITH AB BLOW OUT OCCURED ON LEFT ENGINE ABOVE 2.6 MACH. CONSIDERABLE ENGINE TRINNING WAS REQUIRED THROUGHOUT THE FLIGHT. SAS YAW B CHANNEL MALFUNCTIONED DURING CLIMB OUT BUT RESET WITH HO PROBLEM IT AGAIN MALFUNCTIONED ON GROUND CHECK AFTER LANDING, CAUSE UNKNWOWN. ON LANDING, CHUTE DEPLOY/JETTISON MORNAL.

END OF MESSAGE

USAF review(s) completed.

SECRET

GROUP 1
ERGLUDED FROM AUTOMATTE DOWNGRADING
AND DECLASSIFICATION

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COPY NO.